



Shared Surface Edge Mount Clamp

LO2/08-22




SLAP48: 2 Individual Clamps required per panel
SLAP60: 3 Individual Clamps required per panel
SLAP71: 3 Individual Clamps required per panel

STEP1



STEP2



IMPORTANT NOTE:

- It is advisable to assemble unit on a carpet to avoid scratch.
- Check to be sure that you have all parts and hardware.
- Don't tighten all screws/bolts until all completely assembled.
- It is recommended to require 2 persons to complete the assembling.